

## WEST Search History

DATE: Thursday, January 18, 2007

| <u>Hide?</u>  | <u>Set</u> | <u>Name</u>  | <u>Query</u> | <u>Hit Count</u> |
|---|------------|--|--------------|------------------|
| <i>DB=PGPB,USPT,EPAB,JPAB,DWPI,TDBD; PLUR=YES; OP=ADJ</i> |            |  |              |                  |
| <input type="checkbox"/>                                  | L9         | l6 and L8  |              | 12               |
| <input type="checkbox"/>                                  | L8         | (700/245? or 318/568.12,568.18,568.19,568.22 or 901/1).ccls.   |              | 1652             |
| <input type="checkbox"/>                                  | L7         | correct\$5 and displacement and L6   |              | 34               |
| <input type="checkbox"/>                                  | L6         | angle same measuring and joint same angle and motion and torque and command and control and correction |              | 78               |
| <input type="checkbox"/>                                  | L5         | ('4601468')!.ABPN1,NRPN,PN,TBAN,WKU.   |              | 2                |
| <input type="checkbox"/>                                  | L4         | angle measuring and joint same angle and motion and torque and command and control and correction      |              | 9                |
| <input type="checkbox"/>                                  | L3         | ('20050166413'  '20030025473'  '6919701'  '6413229'  '6042555')!.ABPN1,NRPN,PN,TBAN,WKU.               |              | 8                |
| <input type="checkbox"/>                                  | L2         | angle measuring and joint angle and motion and torque and command                                      |              | 6                |
| <input type="checkbox"/>                                  | L1         | angle measuring and joint angle and motion torque command  |              | 1                |

END OF SEARCH HISTORY